

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. प्रा.प. ८/२०२/०२२Date: 20/09/2022

It is certified that an inspection team headed by Ms. Vijaykumar Sasnaik - Chief officer. (Name of Officers with designation) from Nagar Parishad, Talegaon Dabhade, Pune (Name of Department/Office) inspected the Mount St. Ann High School, Vishnupuri, Talegaon (D) (Name- & Address of the School) on 20/09/2022 and found that the Mount St. Ann High School, Vishnupuri, Talegaon (D) Pune (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T Govt.

The above valid for a period of 3 years.

Signature with Seal: [Signature]Name: मुख्याधिकारीDesignation: तळेगाव दाभाडे नगरपरिषद

To

The Principal,
Mount St. Ann High School,
Talegaon Dabhade, Pune.
(Name & Address of the Institution)